

Leuven, October 5th, 2021

End-of-life notification – AsteRx SB ProDirect

This letter serves as formal notification of our decision to end the life of Septentrio AsteRx SB ProDirect GNSS receiver.

This decision was made as part of our on-going product lifecycle management process, allowing us to offer a replacement product integrating the latest OEM technology available.

Affected Products

The following product codes can be ordered until, and not later than, 28 February 2022 (last time buy date) and can be delivered up to 01 September 2022 (last time delivery date).

Description	Part Number
AsteRx SB ProDirect - C	410332B1884
AsteRx SB ProDirect - M	410332B1882
SM-AsteRx SB ProDirect	410332B1881

Replacement Products

The direct successor of the discontinued product line is the **AsteRx SB3**. The AsteRx SB3 offers superior performance and is pin-to-pin and footprint compatible with the AsteRx SB ProDirect, making the transition seamless.

Description	Part Number
AsteRx SB3 Pro	410384
AsteRx SB3 Pro+	410385

We invite you to discover the capabilities of the AsteRx SB3 Pro and Pro+ by checking our website:

<https://www.septentrio.com/en/products/gnss-receivers/rover-base-receivers/integrated-gnss-receivers>

Warranty & Support

Standard warranty & support conditions apply as indicated in the sales contract. Software maintenance will be ended by 01 September 2023 and repairs will be offered until 01 September 2024. Septentrio keeps the right at its own discretion to decide on the best way to provide customers with a repair solution (considering product and components availability) while still providing the best standard of service and support to its customers. Broken units can,

EMEA

Greenhill Campus (HQ)
Interleuvenlaan 15i
3001 Leuven, **Belgium**

Espoo, **Finland**

Americas

Suite 200
23848 Hawthorne Blvd
Torrance, CA 90505, **USA**

[septentrio.com/contact](https://www.septentrio.com/contact)

Asia-Pacific

Shanghai, **China**
Yokohama, **Japan**
Seoul, **Korea**

[septentrio.com](https://www.septentrio.com)





if possible, still be fixed by our Repair Service until end of the warranty and support period. In such case, please follow the standard Septentrio's RMA procedure. While Septentrio regrets any inconvenience this announcement may cause, we appreciate our business relationship and are fully committed to supply your current and future product requirements.

For additional information on Septentrio products, please contact your local sales representative (sales@septentrio.com) or the Customer Support Portal at <https://www.septentrio.com/en/support>.

EMEA

Greenhill Campus (HQ)
Interleuvenlaan 15i
3001 Leuven, **Belgium**

Espoo, **Finland**

Americas

Suite 200
23848 Hawthorne Blvd
Torrance, CA 90505, **USA**

[septentrio.com/contact](https://www.septentrio.com/contact)

Asia-Pacific

Shanghai, **China**
Yokohama, **Japan**
Seoul, **Korea**

[septentrio.com](https://www.septentrio.com)

